



AC Charge mode on our 18kpv is changing from configured settings. We don't know why. Our default run mode is peak shaving and AC Charge set for voltage, but those settings got changed somehow .

Two scenarios:

1) Using App to "Start Quick Charge" can cause the change.





2) More worrisome, AC Charge settings changed without our knowledge.



After AC Charge settings changed to

incorrect settings, we no longer run on battery.

Incorrect AC Charge settings randomly occur.



) End voltage was changed to 59?

) AC Charge Based On changed to "Time",  
should be "SOC/Voltage"